

Please print or type. (Form designed for use on elite (12-pitch typewriter).)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C.A.D.0.8.6.5.1.0.0.0.5	Manifest Document No. 911300	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address 19503 S. Normandie Avenue Torrance, CA 90502 213 533-6677 K. L. Anderson 722 M/S C6-10				A. State Manifest Document Number 89479136	
4. Generator's Phone ( )				B. State Generator's ID H.A.H.Q.3.6.0.0.5.6.9.8	
5. Transporter 1 Company Name U.S. SERVICES, INC.		6. US EPA ID Number C.A.D.0.5.2.4.5.3.1.0.7		C. State Transporter's ID 113178	
7. Transporter 2 Company Name		8. US EPA ID Number		D. Transporter's Phone (714)371-1461	
9. Designated Facility Name and Site Address USPCI Grassy Mountain Facility U.S. Pollution Control, Inc. 3 Mi.E., 7 Mi.N. Knolls Ex. 41 Clive, Dt. 84074		10. US EPA ID Number U.T.D.9.9.1.3.0.1.7.4.8		E. State Transporter's ID	
				F. Transporter's Phone	
				G. State Facility's ID	
				H. Facility's Phone (801)534-0054	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol
a. Waste Corrosive Solid, n.o.s., Corrosive Material UN1759, (D002 & D007).		0101	DIT	48310	P
b.					
c.					
d.					
J. Additional Descriptions for Materials Listed Above (11a) Soil contaminated with Chromic Acid from Tank Demo. Sample I.D.# GM89-1463-89 Profile # 15189		K. Handling Codes for Wastes Listed Above a. b. c. d.			
15. Special Handling Instructions and Additional Information Guide #60. Wear proper protective clothing when handling. Return to GEN. if rejected. 445		Appointment # 46296 7/13/90 PROFILE #15189 HAULER SITE			
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.  If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name Kris L. Anderson Agent for M.D.A.C.		Signature <i>[Signature]</i>		Month Day Year 9 7 1 2 9 0	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name DWAYNE HIGGINBOTHAM		Signature <i>[Signature]</i>		Month Day Year 10 7 1 2 9 0	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name JOHN W. HAIGHT		Signature <i>[Signature]</i>		Month Day Year 07 11 3 19 0	

Do Not Write Below This Line

Yellow: TSDF SENDS THIS COPY TO GENERATOR WITHIN 30 DAYS



Please print or type. (Form designed for use on elite (12-pitch typewriter).)

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>C, A, D, 0, 8, 6, 5, 1, 0, 0, 0, 5</b>		Manifest Document No. <b>91300</b>		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address <b>19503 S. Normandie Avenue Torrance, CA 90502</b>						A. State Manifest Document Number <b>89479136</b>			
						B. State Generator's ID <b>H, A, H, Q, 3, 6, 0, 0, 5, 6, 9, 8</b>			
4. Generator's Phone (213) <b>539-6677 K. L. Anderson 722 M/S C6-10</b>						C. State Transporter's ID <b>113170</b>			
5. Transporter 1 Company Name <b>U.S. SERVICES, INC.</b>						D. Transporter's Phone <b>(714)371-1461</b>			
7. Transporter 2 Company Name						E. State Transporter's ID			
8. US EPA ID Number						F. Transporter's Phone			
9. Designated Facility Name and Site Address <b>USPCI Grassy Mountain Facility U.S. Pollution Control, Inc. 3 Mi. E. 7 Mi. N. Knolls Ex. 41 Clive, Ot. 84074</b>						G. State Facility's ID			
10. US EPA ID Number <b>U, T, D, 9, 9, 1, 3, 0, 1, 7, 4, 8</b>						H. Facility's Phone <b>(801)534-0054</b>			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)					12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.	
a. <b>Waste Corrosive Solid, n.o.s., Corrosive Material UN1759, (D002 &amp; D007).</b>					<b>0101</b>	<b>DT</b>	<b>48310</b>	<b>P</b>	State <b>611</b>
									EPA/Other <b>D002D007</b>
									State
									EPA/Other
c.									State
d.									State
J. Additional Descriptions for Materials Listed Above <b>(11a) Soil contaminated with Chromic Acid from Tank Demo. Sample I.D.# G409-1463-89 Profile # 15189</b>					K. Handling Codes for Wastes Listed Above				
					a.		b.		
					c.		d.		
15. Special Handling Instructions and Additional Information <b>Guide #60. Wear proper protective clothing when handling. Return to GEN. if rejected. 445</b>									
16. <b>GENERATOR'S CERTIFICATION:</b> I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.  If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.									
Printed/Typed Name <b>Kris L. Anderson Agent for M.D.A.C.</b>					Signature <i>[Signature]</i>			Month Day Year <b>9 7 1 2 9 0</b>	
17. Transporter 1 Acknowledgement of Receipt of Materials									
Printed/Typed Name <b>DWAYNE HIGGINBOTHAM</b>					Signature <i>[Signature]</i>			Month Day Year <b>10 7 1 2 9 0</b>	
18. Transporter 2 Acknowledgement of Receipt of Materials									
Printed/Typed Name					Signature			Month Day Year	
19. Discrepancy Indication Space									
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.									
Printed/Typed Name					Signature			Month Day Year	

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

89479136

GENERATOR

TRANSPORTER

FACILITY